

建物概要 table with columns for building name, location, area, and evaluation details.

評価結果 summary table showing overall score (73.7/100), star rating (4 stars), and category breakdown.

1. エネルギー/温暖化ガス section with sub-tables for energy use, GHG emissions, and efficiency.


2. 水 section with sub-tables for water usage and conservation measures.

3. 資源利用/安全 section with sub-tables for seismic safety, material recycling, and equipment maintenance.

4. 生物多様性/敷地 section with sub-tables for biodiversity, soil quality, and disaster risk.

5. 屋内環境 section with sub-tables for natural light, ventilation, and indoor air quality.

6. ホールライフカーボンの評価 [任意] section for optional carbon footprint evaluation.



環境性能の特徴

- ・エネルギー・水使用量の実績値が高得点であり省エネルギー性能・節水性能が高い。
- ・新耐震基準を満たしている。
- ・構造・非構造材でのリサイクル材利用率が高く、再生材利用に配慮されている。
- ・廃棄物処理負荷抑制対策が適切に行われている。
- ・維持管理への対策がなされている。
- ・徒歩8分圏内に交通公共機関があり利便性が高い。