

建物概要 table with columns for building name, location, area, and evaluation details.

評価結果 summary table showing overall score (74.8/100) and hall carbon footprint evaluation.

1. エネルギー/温暖化ガス section with sub-items 1.1 to 1.4 and associated metrics.


2. 水 section with sub-items 2.1 to 2.3 and associated metrics.

3. 資源利用/安全 section with sub-items 3.1 to 3.4 and associated metrics.

4. 生物多様性/敷地 section with sub-items 4.1 to 4.4 and associated metrics.

5. 屋内環境 section with sub-items 5.1 to 5.3 and associated metrics.

6. ホールライフカーボンの評価 [任意] section with sub-items and associated metrics.



**環境性能の特徴**

- ・エネルギーの計算値/実績値、水使用の実績値が高得点であり省エネルギー性能が高い。
- ・新耐震基準を満たしている。
- ・非構造材料にリサイクル資材を使用している。
- ・敷地内の生物多様性向上に取り組んでいる。
- ・徒歩6分圏内に交通公共機関(鉄道駅)があり利便性が高い。
- ・自然災害リスクへの対策が講じられている。
- ・維持管理が適切に行われており、屋内環境も良好である。