

建物概要 table with columns for building name, location, area, and evaluation details.

評価結果 summary table showing overall score (71.3/100) and star rating (4 stars).

1. エネルギー/温暖化ガス section with sub-tables for energy use and GHG emissions.


2. 水 section with sub-tables for water usage and conservation measures.

3. 資源利用/安全 section with sub-tables for seismic safety and resource efficiency.

4. 生物多様性/敷地 section with sub-tables for biodiversity and site characteristics.

5. 屋内環境 section with sub-tables for indoor air quality, lighting, and thermal comfort.

6. ホールライフカーボンの評価 [任意] section for optional carbon footprint evaluation.



**環境性能の特徴**

- ・エネルギー・水使用量の実績値が高得点であり省エネルギー性能・節水性能が高い。
- ・新耐震基準を満たしている。
- ・非構造材料でのリサイクル材利用率が高く、再生材利用に配慮されている。
- ・廃棄物処理負荷抑制対策が適切に行われている。
- ・生物多様性向上への配慮がなされている。
- ・徒歩8分圏内に交通公共機関があり利便性が高い。