

建物概要 table with columns for building name, location, area, and evaluation details.

評価結果 summary table showing overall score (69.4/100) and star rating (4 stars).

1. エネルギー/温暖化ガス section table with sub-items 1.1 to 1.4 and associated metrics.


2. 水 section table with sub-items 2.1 to 2.3 and associated metrics.

3. 資源利用/安全 section table with sub-items 3.1 to 3.4 and associated metrics.

4. 生物多様性/敷地 section table with sub-items 4.1 to 4.4 and associated metrics.

5. 屋内環境 section table with sub-items 5.1 to 5.3 and associated metrics.

6. ホールライフカーボンの評価 [任意] section table for optional carbon footprint evaluation.



環境性能の特徴

- ・エネルギー・水使用量の実績値が高得点であり省エネルギー性能・節水性能が高い。
- ・新耐震基準を満たしている。
- ・非構造材でのリサイクル材利用率が高く、再生材利用に配慮されている。
- ・廃棄物処理負荷抑制対策が適切に行われている。
- ・生物多様性向上への配慮がなされている。
- ・徒歩8分圏内に交通公共機関があり利便性が高い。