

建物概要 table with columns for building name, location, area, and evaluation details.

評価結果 summary table showing overall score (79.0/100) and hallmarks evaluation.

1. エネルギー/温暖化ガス section with sub-tables for energy performance and carbon footprint.


2. 水 section with sub-tables for water usage and conservation measures.

3. 資源利用/安全 section with sub-tables for seismic safety, recycling, and equipment maintenance.

4. 生物多様性/敷地 section with sub-tables for biodiversity and site safety.

5. 屋内環境 section with sub-tables for natural light, ventilation, and indoor air quality.

6. ホールライフカーボンの評価 [任意] section for optional hallmarks evaluation.



環境性能の特徴

- ・エネルギー使用の計算値/実績値、水使用の実績値及び仕様評価が高得点であり省エネルギー性能が高い。
- ・新耐震基準を満たしている。
- ・敷地内の生物多様性向上に取り組んでいる。
- ・徒歩4分圏内に交通公共機関(鉄道駅)があり利便性が高い。
- ・自然災害リスクへの対策が講じられている。
- ・維持管理が適切に行われており、屋内環境も良好である。