

建物概要 table with columns for building name, location, area, and evaluation details.

評価結果 summary table showing overall score (71.9/100), star rating (4 stars), and hall carbon footprint evaluation.

1. エネルギー/温暖化ガス section with sub-items 1.1 to 1.4 and associated metrics like energy consumption and GHG emissions.


2. 水 section with sub-items 2.1 to 2.3 and metrics for water usage and recycling.

3. 資源利用/安全 section with sub-items 3.1 to 3.4 and metrics for seismic safety, recycling, and equipment maintenance.

4. 生物多様性/敷地 section with sub-items 4.1 to 4.4 and metrics for biodiversity and disaster risk.

5. 屋内環境 section with sub-items 5.1 to 5.3 and metrics for natural light, ventilation, and indoor air quality.

6. ホールライフカーボンの評価 [任意] section for optional hall carbon footprint evaluation.



環境性能の特徴

- ・エネルギー使用の計算値/実績値が概ね高得点であり省エネルギー性能が高い。
- ・水使用の実績値及び仕様評価が高得点であり節水性能が高い。
- ・新耐震基準を満たしている。
- ・非構造材料にリサイクル資材を使用している。
- ・徒歩7分圏内に交通公共機関(鉄道駅)があり利便性が高い。
- ・維持管理が適切に行われている。